







**Inventory of historically and culturally significant buildings and complexes in Aceh**





<b>No.</b>	009
<b>Name</b>	Ruko China (Chinese Shop houses)
<b>Location</b>	Peunayong (Jl. R.A Kartini)
<b>Present and Past Function</b>	Shop Housese
<b>Date of Inventory</b>	11 August 2005
<b>Literature</b>	Inventory Team

<b>A: the building</b>									
A.1: Plan	-								
A.2: Facades	<table border="1"> <tr> <td align="center">  </td> <td align="center">  </td> </tr> <tr> <td align="center">Front Façade</td> <td align="center">Side Façade</td> </tr> <tr> <td align="center">  </td> <td></td> </tr> <tr> <td align="center">Back Façade</td> <td></td> </tr> </table>			Front Façade	Side Façade			Back Façade	
									
Front Façade	Side Façade								
									
Back Façade									

A.3: typical design details			
	Roof shape	Windows	Arch Corridor
			
	Windows	Roof Ornament	Detail Coloumn
	<b>B: construction of the building</b>		
	B.1: Construction method	Typical shophouse construction, masonry party walls spanned by timber purlins, beams and joists, timber floor boards.	
B.2: construction details			
	Wooden Ceiling	Brick Wall Structure	Roof Structure
			
	Joint arch, beam and column	Brick Wall Structure	Bracket and overhang

B.3: cross-section of the building			
<b>C: the interior of the building</b>			
C.1: interior details			
	Wooden Stairs	Wooden Door Frame	
			
	Ornamental end of iron tie rod	Ventilation	
<b>D: State of repairs of the building</b>	Some of the buildings only need minor repairs especially for the interior, but several buildings need to be rebuilt since it was totally destroyed by Tsunami December 2004.		
<b>E: history of the building</b>			
E.1: date of construction	Late 19 <sup>th</sup> century to early 20 <sup>th</sup> century		
E.2: ownership	Private		
E.3: use of the building	Ground floor is used for shop and the upper floor was used a house.		
E.4: changes to the building	Some of the buildings are still in original condition, some have been slightly modified, but the rest were destroyed by Tsunami December 2004.		
<b>F: urban context of the building</b>			



<p>F.1: location</p>	
<p>F.2: description</p>	<p>This row of shop houses was located in the Chinese enclave in the Peunayong area and it was bordered with Krueng Aceh river.</p>
<p>F.3: history of the neighbourhood</p>	<p>-</p>
<p>F.4: location of the neighbourhood in the city</p>	
<p><b>G: summary of the historical value and development of the building</b></p>	<p>This row of old shop houses in the Peunayong Chinese quarter is still original and functions as dwellings and shops of the Chinese in Banda Aceh. It is located along the main commercial area by the Kreung Aceh River, the main river which divides the town. Some of the shop houses survived the natural disaster. #</p>

