










**Inventory of historically and culturally significant buildings and complexes in Aceh**




After Tsunami

<b>No.</b>	010
<b>Name</b>	Art-Deco 'Jengki' Shophouse (Ruko bergaya Jengki)
<b>Location</b>	Peunayong (Jln. R.A Kartini), Banda Aceh
<b>Present and Past Function</b>	Shophouse/office
<b>Date of Inventory</b>	11 August 2005
<b>Literature</b>	Inventory Team


<b>A: the building</b>			
A.1: Plan	-		
A.2: Facades	<p>Front Facade</p>		
A.3: typical design details	<table border="1"> <tr> <td align="center"> <p>Balcony</p> </td> <td align="center"> <p>'Jengki' Column Ornament</p> </td> </tr> </table>	<p>Balcony</p>	<p>'Jengki' Column Ornament</p>
<p>Balcony</p>	<p>'Jengki' Column Ornament</p>		

			
	Window Railing	Window grill	
<b>B: construction of the building</b>			
B.1:	Material used for main structure is brick, wooden floor and stairs.		
B.2: construction details			
			
	Wooden floor	Wooden Stairs	Wooden Stairs
B.3: cross-section of the building	-		
<b>C: the interior of the building</b>			
C.1: interior details			
			
	Lamp	Door	
			
	Door	Door frame	

<b>D: State of repairs of the building</b>	The building is in good condition.
<b>E: history of the building</b>	
E.1: date of construction	Probably around 1960's
E.2: ownership	Private (Mr. Jamil)
E.3: use of the building	Shophouse/Office
E.4: changes to the building	There is no significant change of this building; generally, it is still in original condition only the interior lay-out has changed several times. It looks like the front entrance has been enlarged, and perhaps the sunscreens around the windows could have been removed but I can't really tell from the photos. Is it a detached house or two houses as one? I think it was formerly a residential house.
<b>F: urban context of the building</b>	
F.1: location	



F.2: description	This building was located in business area (Peunayong) on Jl. W.R. Supratman. It can be reached for about 5 minutes from the heart of city.
F.3: history of the neighbourhood	Business area (Chinese enclave), most of the buildings are shophouses. There are also other Art-Deco 'Jengki' buildings in this area. Art Deco – Jengki.
F.4: location of the neighbourhood in the city	

	
<p><b>G: summary of the historical value and development of the building</b></p>	<p>This building is assumed to have been built in the 1960's. Formerly it functioned as a shop but currently using as a consultant's office.#</p>